


Chapter 11: Applications and Processing of Metal Alloys

ISSUES TO ADDRESS...

- How are metal alloys classified and what are their common applications?
- What are some of the common fabrication techniques for metals?
- What heat treatment procedures are used to improve the mechanical properties of both ferrous and nonferrous alloys?



Classification of Metal Alloys




Steels

Low Alloy								High Alloy
	low carbon <0.25 wt% C	Med carbon 0.25-0.6 wt% C	high carbon 0.6-1.4 wt% C					
Name	plain	HSLA	plain	heat treatable	plain	tool	stainless	
Additions	none	Cr, V Ni, Mo	none	Cr, Ni Mo	none	Cr, V, Mo, W	Cr, Ni, Mo	
Example	1010	4310	1040	4340	1095	4190	304, 409	
Hardenability	0	+	+	++	++	+++	varies	
TS	-	0	+	++	+	++	varies	
EL	+	+	0	-	-	--	++	
Uses	auto struc. sheet	bridges towers press. vessels	crank shafts bolts hammers	pistons gears wear applic. blades	wear applic.	drills saws dies	high T applic. turbines furnaces	Very corros. resistant

increasing strength, cost, decreasing ductility

Based on data provided in Tables 11.1(b), 11.2(b), 11.3, and 11.4, Callister & Rethwisch 8e.

Refinement of Steel from Ore



Ferrous Alloys

Iron-based alloys

- Steels
- Cast Irons

Nomenclature for steels (AISI/SAE)

10xx Plain Carbon Steels

11xx Plain Carbon Steels (resulfurized for machinability)

15xx Mn (1.00 - 1.65%)

40xx Mo (0.20 ~ 0.30%)

43xx Ni (1.65 - 2.00%), Cr (0.40 - 0.90%), Mo (0.20 - 0.30%)

44xx Mo (0.5%)

where xx is wt% C x 100

example: 1060 steel – plain carbon steel with 0.60 wt% C

Stainless Steel >11% Cr



Cast Irons

- Ferrous alloys with > 2.1 wt% C
 - more commonly 3 - 4.5 wt% C
- Low melting – relatively easy to cast
- Generally brittle
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{ Fe} (\alpha) + \text{C (graphite)}$$
 - generally a slow process




Fe-C True Equilibrium Diagram

Graphite formation promoted by

- $\text{Si} > 1 \text{ wt\%}$
- slow cooling

Adapted from Fig. 11.2,
Callister & Rethwisch 8e.
[Fig. 11.2 adapted from
Binary Alloy Phase Diagrams, 2nd ed.,
Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International,
Materials Park, OH, 1990.]



Types of Cast Iron

Gray iron


- graphite flakes
- weak & brittle in tension
- stronger in compression
- excellent vibrational dampening
- wear resistant

Adapted from Fig.
11.3(a) & (b),
Callister &
Rethwisch 8e.



Ductile iron

- add Mg and/or Ce
- graphite as nodules not flakes
- matrix often pearlite – stronger but less ductile



Types of Cast Iron (cont.)

White iron


- < 1 wt% Si
- pearlite + cementite
- very hard and brittle

Adapted from Fig.
11.3(c) & (d),
Callister &
Rethwisch 8e.



Malleable iron


- heat treat white iron at 800-900°C
- graphite in rosettes
- reasonably strong and ductile



Types of Cast Iron (cont.)

Compacted graphite iron

- relatively high thermal conductivity
- good resistance to thermal shock
- lower oxidation at elevated temperatures




Adapted from Fig. 11.3(e),
Callister & Rethwisch 8e.



Production of Cast Irons

Adapted from Fig.11.5,
Callister & Rethwisch 8e.



Limitations of Ferrous Alloys

- 1) Relatively high densities
- 2) Relatively low electrical conductivities
- 3) Generally poor corrosion resistance

Nonferrous Alloys

- Cu Alloys

Brass: Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

Bronze : Sn, Al, Si, Ni are subst. impurities (bushings, landing gear)

Cu-Be: precip. hardened for strength

- Ti Alloys

-relatively low ρ : 4.5 g/cm^3

vs 7.9 for steel

-reactive at high T 's

-space applic.

- Al Alloys

-low ρ : 2.7 g/cm^3

-Cu, Mg, Si, Mn, Zn additions

-solid sol. or precip.

strengthened (struct. aircraft parts & packaging)

- Mg Alloys

-very low ρ : 1.7 g/cm^3

-ignites easily

-aircraft, missiles

- Refractory metals

-high melting T 's

-Nb, Mo, W, Ta

NonFerrous Alloys

- Noble metals

-Ag, Au, Pt

-oxid./corr. resistant



Metal Fabrication

- How do we fabricate metals?
 - Blacksmith - hammer (forged)
 - Cast molten metal into mold
- Forming Operations
 - Rough stock formed to final shape

Hot working

vs.

Cold working


- Deformation temperature high enough for recrystallization
- Large deformations

- Deformation below recrystallization temperature
- Strain hardening occurs
- Small deformations


Metal Fabrication Methods (i)

FORMING

- Forging (Hammering; Stamping)
(wrenches, crankshafts)



- Drawing
(rods, wire, tubing)




die must be well lubricated & clean

CASTING


MISCELLANEOUS

- Rolling (Hot or Cold Rolling)
(I-beams, rails, sheet & plate)



Adapted from
Fig. 11.8,
Callister &
Rethwisch 8e.


- Extrusion
(rods, tubing)



ductile metals, e.g. Cu, Al (hot)
Chapter 11 - 15



Metal Fabrication Methods (ii)




- **Casting**- mold is filled with molten metal
 - metal melted in furnace, perhaps alloying elements added, then **cast** in a mold
 - common and inexpensive
 - gives good production of shapes
 - weaker products, internal defects
 - good option for brittle materials

Metal Fabrication Methods (iii)

FORMING

- **Sand Casting**

(large parts, e.g.,
auto engine blocks)



CASTING


MISCELLANEOUS

- What material will withstand $T > 1600^{\circ}\text{C}$ and is inexpensive and easy to mold?
- Answer: sand!!!
- To create mold, pack sand around form (pattern) of desired shape


Metal Fabrication Methods (iv)




- **Investment Casting**
(low volume, complex shapes
e.g., jewelry, turbine blades)
- **Stage I** — Mold formed by pouring plaster of paris around wax pattern. Plaster allowed to harden.
- **Stage II** — Wax is melted and then poured from mold—hollow mold cavity remains.
- **Stage III** — Molten metal is poured into mold and allowed to solidify.



Metal Fabrication Methods (v)




- **Die Casting**
 - high volume
 - for alloys having low melting temperatures
- **Continuous Casting**
 - simple shapes
 - (e.g., rectangular slabs, cylinders)



Metal Fabrication Methods (vi)

FORMING


- Powder Metallurgy
(metals w/low ductilities)



CASTING

MISCELLANEOUS

- Welding
(when fabrication of one large part is impractical)



- Heat-affected zone:
(region in which the microstructure has been changed).

Adapted from Fig. 11.9, *Callister & Rethwisch 8e.*
(Fig. 11.9 from *Iron Castings Handbook*, C.F. Walton and T.J. Opar (Ed.), 1981.)

Thermal Processing of Metals

Annealing: Heat to T_{anneal} , then cool slowly.

- **Stress Relief:** Reduce stresses resulting from:
 - plastic deformation
 - nonuniform cooling
 - phase transform.

- **Spheroidize** (steels): Make very soft steels for good machining. Heat just below $T_{\text{eutectoid}}$ & hold for 15-25 h.

Types of Annealing

- **Process Anneal:** Negate effects of cold working by (recovery/ recrystallization)

- **Full Anneal** (steels): Make soft steels for good forming. Heat to get γ , then furnace-cool to obtain coarse pearlite.


- **Normalize** (steels): Deform steel with large grains. Then heat treat to allow recrystallization and formation of smaller grains.



Heat Treatment Temperature-Time Paths


- a) Full Annealing
- b) Quenching
- c) Tempering (Tempered Martensite)

Fig. 10.25,
Callister &
Rethwisch 8e.




Hardenability -- Steels

- Hardenability – measure of the ability to form martensite
- Jominy end quench test used to measure hardenability.



Adapted from Fig. 11.11,
Callister & Rethwisch 8e.
(Fig. 11.11 adapted from
A.G. Guy, *Essentials of
Materials Science*,
McGraw-Hill Book
Company, New York,
1978.)


- Plot hardness versus distance from the quenched end.



Adapted from Fig. 11.12,
Callister & Rethwisch 8e.

Reason Why Hardness Changes with Distance

- The cooling rate decreases with distance from quenched end.




Adapted from Fig. 11.13, Callister & Rethwisch 8e. (Fig. 11.13 adapted from H. Boyer (Ed.) *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, American Society for Metals, 1977, p. 376.)


Hardenability vs Alloy Composition

- Hardenability curves for five alloys each with, $C = 0.4$ wt% C

Adapted from Fig. 11.14, *Callister & Rethwisch 8e*. (Fig. 11.14 adapted from figure furnished courtesy Republic Steel Corporation.)



- "Alloy Steels"
(4140, 4340, 5140, 8640)
 - contain Ni, Cr, Mo (0.2 to 2 wt%)
 - these elements shift the "nose" to longer times (from A to B)
 - martensite is easier to form



Influences of Quenching Medium & Specimen Geometry


- Effect of quenching medium:

Medium	Severity of Quench	Hardness
air	low	low
oil	moderate	moderate
water	high	high

- Effect of specimen geometry:

When surface area-to-volume ratio increases:

- cooling rate throughout interior increases
- hardness throughout interior increases





Position	Cooling rate	Hardness
center	low	low
surface	high	high



Precipitation Hardening

- Particles impede dislocation motion.
- Ex: Al-Cu system
- Procedure:
 - Pt A: solution heat treat (get α solid solution)
 - Pt B: quench to room temp. (retain α solid solution)
 - Pt C: reheat to nucleate small θ particles within α phase.
- Other alloys that precipitation harden:
 - Cu-Be
 - Cu-Sn
 - Mg-Al



Adapted from Fig. 11.22, Callister & Rethwisch 8e.



Adapted from Fig. 11.24, Callister & Rethwisch 8e.
(Fig. 11.24 adapted from J.L. Murray, *International Metals Review* **30**, p.5, 1985.)

Influence of Precipitation Heat Treatment on TS , $\%EL$

- 2014 Al Alloy:
- Maxima on TS curves.
- Increasing T accelerates process.
- Minima on $\%EL$ curves.



Adapted from Fig. 11.27, Callister & Rethwisch 8e. (Fig. 11.27 adapted from *Metals Handbook: Properties and Selection: Nonferrous Alloys and Pure Metals*, Vol. 2, 9th ed., H. Baker (Managing Ed.), American Society for Metals, 1979. p. 41.)

Summary

- Ferrous alloys: steels and cast irons
- Non-ferrous alloys:
 - Cu, Al, Ti, and Mg alloys; refractory alloys; and noble metals.
- Metal fabrication techniques:
 - **forming, casting**, miscellaneous.
- Hardenability of metals
 - measure of ability of a steel to be heat treated.
 - increases with alloy content.
- Precipitation hardening
 - hardening, strengthening due to formation of precipitate particles.
 - Al, Mg alloys precipitation hardenable.